

KnowledgeBase Article 2053


Quality Master

The Quality Master is a powerful tool forcing quality checks of various types upon the MES Touch user while performing their duties in the manufacturing process. Quality attributes may be "Qualitative", requiring pass / fail information, or "Quantitative", requiring specific readings and measurements. Quality checks can be forced upon a certain percentage of the pieces completed or a very specific number of pieces, (IE every piece, or every tenth piece, etc.) When the user reaches the quantity specified, the MES system will not permit further entry of parts until the user completes the required quality check.


Setup of the Quality Master is dependent upon complete part information. In addition, the Quality Master is assigned to a specific routing sequence. The Quality Master may be assigned to any or as many routing sequences as required. Further, multiple quality masters may be assigned to any given sequence.

To create a Quality Master:


1. Navigate to Engineering Management > Part List and select (double-click) the part desired




2. Open the Routing and select (double-click) the routing sequence desired




3. Open the Quality Master and click the "Add New" button to create a new Quality Master for this routing sequence.




- 4. Complete the required (red outline) information on the Quality Master.
 - a. The number on the Quality Master is the order in which the quality checks should be performed. As with most numbering in Guardian, it is recommended to use 4 digits to allow for additional attributes to be added if required, IE 0010, 0020, etc.
 - b. The name on the Quality Master is the Quality check required…IE "Check Hole Diameter" or "Check Temperature".



5. If the Quality check is "Qualitative", select the Type and complete the "Check Percent" or "Check every _ of _ pieces". Save



- 6. If the Quality check is "Quantitative", select the Type and complete the Minimum, Alert Minimum, Target, Alert Maximum and Maximum fields.
 - a. The system can calculate the Target value automatically by checking the "Calculate Target" checkbox, however, the Minimum and Maximum must be entered first.



7. Complete the "Check Percent" or "Check every _ of _ pieces". Save.